

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

Approve to Publish by: Lolita Welch

Procurement Management Professional

#	Description	Quantity	Unit of Measure	Clark Construction Company		Commercial Contracting Corporation		Detroit Contracting Engineering, Inc.		LGC Global, Inc.		Pullman SST, Inc.	
				Unit Price	Total Cost	Unit Price	Total Cost	Unit Price	Total Cost	Unit Price	Total Cost	Unit Price	Total Cost
#1	3.0 Imlay Station	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#2	3.14 Removal of settled material from reservoir interior	80	CY	\$80.00	\$6,400.00	\$120.00	\$9,600.00	\$80.00	\$6,400.00	\$96.35	\$7,708.00	\$88.00	\$7,040.00
#3	3.15 Supplemental Dewatering	30	DAY	\$1,741.00	\$52,230.00	\$3,474.00	\$104,220.00	\$1,300.00	\$39,000.00	\$1,014.79	\$30,443.70	\$1,104.00	\$33,120.00
#4	3.16.A Type I Crack Repair - Leaking Crack Repair, Less Than 6-ft Above Floor	1480	LF	\$25.25	\$37,370.00	\$33.00	\$48,840.00	\$36.00	\$53,280.00	\$26.77	\$39,619.60	\$27.00	\$39,960.00
#5	3.16.B Type I Crack Repair - Leaking Crack Repair, 6-ft and Greater Above Floor	1670	LF	\$26.26	\$43,854.20	\$36.00	\$60,120.00	\$39.00	\$65,130.00	\$27.84	\$46,492.80	\$28.00	\$46,760.00
#6	3.16.C Type I Crack Repair - Leaking Crack Repair, Overhead	3820	LF	\$30.30	\$115,746.00	\$46.00	\$175,720.00	\$40.00	\$152,800.00	\$32.12	\$122,698.40	\$29.00	\$110,780.00
#7	3.17.A Type II Crack Repair - Structural Crack Repair, Less Than 6-ft Above Floor	170	LF	\$24.24	\$4,120.80	\$47.00	\$7,990.00	\$44.00	\$7,480.00	\$25.69	\$4,367.30	\$29.00	\$4,930.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

#8	3.17.B Type II Crack Repair - Structural Crack Repair, 6-ft and Greater Above Floor	190	LF	\$29.55	\$5,614.50	\$53.00	\$10,070.00	\$46.00	\$8,740.00	\$31.32	\$5,950.80	\$31.00	\$5,890.00
#9	3.17.C Type II Crack Repair - Structural Crack Repair, Overhead	430	LF	\$33.84	\$14,551.20	\$35.00	\$15,050.00	\$48.00	\$20,640.00	\$35.87	\$15,424.10	\$35.00	\$15,050.00
#10	3.18.A Type III Crack Repair - Structural Control/Construction Joint Repair, Less Than 6-ft Above Floor	15255	LF	\$6.57	\$100,225.35	\$11.00	\$167,805.00	\$15.00	\$228,825.00	\$6.96	\$106,174.80	\$5.30	\$80,851.50
#11	3.18.B Type III Crack Repair - Structural Control/Construction Joint Repair, 6-ft and Greater Above Floor	16255	LF	\$8.84	\$143,694.20	\$11.00	\$178,805.00	\$17.00	\$276,335.00	\$9.37	\$152,309.35	\$5.30	\$86,151.50
#12	3.19.A RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#13	3.19.B RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#14	3.19.C RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#15	3.20.A Concrete Surface Spall Repair (Less than 2" in depth), Less Than 6-ft Above Floor	600	SF	\$63.63	\$38,178.00	\$66.00	\$39,600.00	\$45.00	\$27,000.00	\$67.45	\$40,470.00	\$96.00	\$57,600.00
#16	3.20.B Concrete Surface Spall Repair (Less than 2" in depth), 6-ft	220	SF	\$81.81	\$17,998.20	\$98.00	\$21,560.00	\$47.00	\$10,340.00	\$86.72	\$19,078.40	\$104.00	\$22,880.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	and Greater Above Floor												
#17	3.20.C Concrete Surface Spall Repair (Less than 2" in depth), Overhead	1810	SF	\$131.30	\$237,653.00	\$80.00	\$144,800.00	\$55.00	\$99,550.00	\$139.18	\$251,915.80	\$119.00	\$215,390.00
#18	3.21.A Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Less Than 6-ft Above Floor	940	SF	\$135.34	\$127,219.60	\$116.00	\$109,040.00	\$89.00	\$83,660.00	\$143.46	\$134,852.40	\$144.00	\$135,360.00
#19	3.21.B Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), 6-ft and Greater Above Floor	340	SF	\$177.51	\$60,353.40	\$132.00	\$44,880.00	\$96.00	\$32,640.00	\$188.16	\$63,974.40	\$178.00	\$60,520.00
#20	3.21.C Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Overhead	2840	SF	\$194.43	\$552,181.20	\$154.00	\$437,360.00	\$108.00	\$306,720.00	\$206.09	\$585,295.60	\$184.00	\$522,560.00
#21	3.22.A Anti-corrosion Rebar Coating, Less Than 6-ft Above Floor	490	LF	\$8.08	\$3,959.20	\$10.00	\$4,900.00	\$50.00	\$24,500.00	\$8.56	\$4,194.40	\$18.00	\$8,820.00
#22	3.22.B Anti-corrosion Rebar Coating, 6-ft and	1110	LF	\$11.11	\$12,332.10	\$17.00	\$18,870.00	\$54.00	\$59,940.00	\$11.78	\$13,075.80	\$22.00	\$24,420.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	Greater Above Floor												
#23	3.23.A Corner Spall Repair, Less Than 6-ft Above Floor	470	LF	\$158.07	\$74,292.90	\$65.00	\$30,550.00	\$94.00	\$44,180.00	\$167.55	\$78,748.50	\$144.00	\$67,680.00
#24	3.23.B Corner Spall Repair, 6-ft and Greater Above Floor	770	LF	\$191.90	\$147,763.00	\$80.00	\$61,600.00	\$98.00	\$75,460.00	\$203.41	\$156,625.70	\$150.00	\$115,500.00
#25	3.23.C RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#26	4.0 Lake Huron Water Treatment Plant - Reservoir No. 1	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#27	4.14 Removal of settled material from reservoir interior	80	CY	\$80.00	\$6,400.00	\$120.00	\$9,600.00	\$80.00	\$6,400.00	\$96.35	\$7,708.00	\$88.00	\$7,040.00
#28	4.15 Supplemental Dewatering	30	DAY	\$1,886.40	\$56,592.00	\$3,474.00	\$104,220.00	\$1,300.00	\$39,000.00	\$1,191.65	\$35,749.50	\$1,104.00	\$33,120.00
#29	4.16.A Type I Crack Repair - Leaking Crack Repair, Less Than 6-ft Above Floor	1110	LF	\$25.76	\$28,593.60	\$33.00	\$36,630.00	\$43.00	\$47,730.00	\$27.30	\$30,303.00	\$29.00	\$32,190.00
#30	4.16.B Type I Crack Repair - Leaking Crack Repair, 6-ft and Greater Above Floor	820	LF	\$27.78	\$22,779.60	\$36.00	\$29,520.00	\$46.00	\$37,720.00	\$29.44	\$24,140.80	\$30.00	\$24,600.00
#31	4.16.C Type I Crack Repair - Leaking Crack Repair, Overhead	3010	LF	\$31.57	\$95,025.70	\$46.00	\$138,460.00	\$47.00	\$141,470.00	\$33.46	\$100,714.60	\$32.00	\$96,320.00
#32	4.17 A Type II Crack Repair - Structural Crack Repair, Less Than 6-ft Above Floor	60	LF	\$33.33	\$1,999.80	\$62.00	\$3,720.00	\$49.00	\$2,940.00	\$35.33	\$2,119.80	\$32.00	\$1,920.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

#33	4.17.B Type II Crack Repair - Structural Crack Repair, 6-ft and Greater Above Floor	50	LF	\$40.91	\$2,045.50	\$57.00	\$2,850.00	\$51.00	\$2,550.00	\$43.36	\$2,168.00	\$33.00	\$1,650.00
#34	4.17.C Type II Crack Repair - Structural Crack Repair, Overhead	160	LF	\$43.69	\$6,990.40	\$51.00	\$8,160.00	\$54.00	\$8,640.00	\$46.30	\$7,408.00	\$37.00	\$5,920.00
#35	4.18.A Type III Crack Repair - Structural Control/Construction Repair, Less Than 6-ft Above Floor	5273	LF	\$7.07	\$37,280.11	\$11.00	\$58,003.00	\$18.00	\$94,914.00	\$7.49	\$39,494.77	\$5.70	\$30,056.10
#36	4.18.B Type III Crack Repair - Structural Control/Construction Repair, 6-ft and Greater Above Floor	5603	LF	\$9.60	\$53,788.80	\$11.00	\$61,633.00	\$20.00	\$112,060.00	\$10.17	\$56,982.51	\$5.70	\$31,937.10
#37	4.19.A RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#38	4.19.B RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#39	4.19.C RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#40	4.20.A Concrete Surface Spall Repair (Less than 2" in depth), Less Than 6-ft Above Floor	130	SF	\$72.47	\$9,421.10	\$69.00	\$8,970.00	\$50.00	\$6,500.00	\$76.82	\$9,986.60	\$101.00	\$13,130.00
#41	4.20.B Concrete Surface Spall Repair (Less than 2" in depth), 6-ft	70	SF	\$104.03	\$7,282.10	\$62.00	\$4,340.00	\$54.00	\$3,780.00	\$110.27	\$7,718.90	\$110.00	\$7,700.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	and Greater Above Floor												
#42	4.20.C Concrete Surface Spall Repair (Less than 2" in depth), Overhead	400	SF	\$139.89	\$55,956.00	\$82.00	\$32,800.00	\$62.00	\$24,800.00	\$148.28	\$59,312.00	\$146.00	\$58,400.00
#43	4.21.A Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Less Than 6-ft Above Floor	210	SF	\$163.62	\$34,360.20	\$114.00	\$23,940.00	\$96.00	\$20,160.00	\$173.44	\$36,422.40	\$172.00	\$36,120.00
#44	4.21.B Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), 6-ft and Greater Above Floor	110	SF	\$186.85	\$20,553.50	\$131.00	\$14,410.00	\$101.00	\$11,110.00	\$198.06	\$21,786.60	\$186.00	\$20,460.00
#45	4.21.C Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Overhead	630	SF	\$209.07	\$131,714.10	\$153.00	\$96,390.00	\$115.00	\$72,450.00	\$221.61	\$139,614.30	\$193.00	\$121,590.00
#46	4.22.A Anti-corrosion Rebar Coating, Less Than 6-ft Above Floor	80	LF	\$9.09	\$727.20	\$16.00	\$1,280.00	\$55.00	\$4,400.00	\$9.64	\$771.20	\$18.00	\$1,440.00
#47	4.22.B Anti-corrosion Rebar Coating, 6-ft and	280	LF	\$11.62	\$3,253.60	\$16.00	\$4,480.00	\$58.00	\$16,240.00	\$12.31	\$3,446.80	\$23.00	\$6,440.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	Greater Above Floor												
#48	4.23 A Corner Spall Repair, Less Than 6-ft Above Floor	50	LF	\$259.32	\$12,966.00	\$75.00	\$3,750.00	\$101.00	\$5,050.00	\$274.88	\$13,744.00	\$171.00	\$8,550.00
#49	4.23.B Corner Spall Repair, 6-ft and Greater Above Floor	80	LF	\$213.62	\$17,089.60	\$77.00	\$6,160.00	\$105.00	\$8,400.00	\$226.43	\$18,114.40	\$183.00	\$14,640.00
#50	4.23.C Corner Spall Repair, Overhead	120	LF	\$233.31	\$27,997.20	\$82.00	\$9,840.00	\$118.00	\$14,160.00	\$247.31	\$29,677.20	\$214.00	\$25,680.00
#51	5.0 Lake Huron Water Treatment Plant Reservoir No. 2	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#52	5.14 Removal of settled material from reservoir interior	80	CY	\$80.00	\$6,400.00	\$120.00	\$9,600.00	\$80.00	\$6,400.00	\$96.35	\$7,708.00	\$88.00	\$7,040.00
#53	5.15 Supplemental Dewatering	30	DAY	\$1,886.40	\$56,592.00	\$3,474.00	\$104,220.00	\$1,300.00	\$39,000.00	\$1,191.65	\$35,749.50	\$1,104.00	\$33,120.00
#54	5.16.A Type I Crack Repair - Leaking Crack Repair, Less Than 6-ft Above Floor	1110	LF	\$25.25	\$28,027.50	\$33.00	\$36,630.00	\$39.00	\$43,290.00	\$26.77	\$29,714.70	\$28.00	\$31,080.00
#55	5.16.B Type I Crack Repair - Leaking Crack Repair, 6-ft and Greater Above Floor	820	LF	\$27.53	\$22,574.60	\$36.00	\$29,520.00	\$42.00	\$34,440.00	\$29.17	\$23,919.40	\$29.00	\$23,780.00
#56	5.16.C Type I Crack Repair - Leaking Crack Repair, Overhead	2850	LF	\$32.32	\$92,112.00	\$46.00	\$131,100.00	\$43.00	\$122,550.00	\$34.26	\$97,641.00	\$30.00	\$85,500.00
#57	5.17.A Type II Crack Repair - Structural Crack Repair,	60	LF	\$32.83	\$1,969.80	\$62.00	\$3,720.00	\$46.00	\$2,760.00	\$34.79	\$2,087.40	\$30.00	\$1,800.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	Less Than 6-ft Above Floor												
#58	5.17.B Type II Crack Repair - Structural Crack Repair, 6-ft and Greater Above Floor	50	LF	\$40.40	\$2,020.00	\$62.00	\$3,100.00	\$48.00	\$2,400.00	\$42.82	\$2,141.00	\$32.00	\$1,600.00
#59	5.17.C Type II Crack Repair - Structural Crack Repair, Overhead	140	LF	\$37.63	\$5,268.20	\$75.00	\$10,500.00	\$50.00	\$7,000.00	\$39.88	\$5,583.20	\$36.00	\$5,040.00
#60	5.18.A Type III Crack Repair - Structural Control/Construction Repair, Less Than 6-ft Above Floor	5273	LF	\$7.07	\$37,280.11	\$11.00	\$58,003.00	\$16.00	\$84,368.00	\$7.49	\$39,494.77	\$5.50	\$29,001.50
#61	5.18.B Type III Crack Repair - Structural Control/Construction Repair, 6-ft and Greater Above Floor	5603	LF	\$9.35	\$52,388.05	\$11.00	\$61,633.00	\$18.00	\$100,854.00	\$9.90	\$55,469.70	\$5.50	\$30,816.50
#62	5.19.A RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#63	5.19.B RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#64	5.19.C RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#65	5.20.A Concrete Surface Spall Repair (Less than 2" in depth), Less Than 6-ft Above Floor	130	SF	\$71.97	\$9,356.10	\$69.00	\$8,970.00	\$47.00	\$6,110.00	\$76.28	\$9,916.40	\$98.00	\$12,740.00
#66	5.20.B Concrete Surface Spall Repair (Less than 2" in	70	SF	\$103.53	\$7,247.10	\$62.00	\$4,340.00	\$49.00	\$3,430.00	\$109.74	\$7,681.80	\$107.00	\$7,490.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	depth), 6-ft and Greater Above Floor												
#67	5.20.C Concrete Surface Spall Repair (Less than 2" in depth), Overhead	400	SF	\$137.87	\$55,148.00	\$82.00	\$32,800.00	\$58.00	\$23,200.00	\$146.14	\$58,456.00	\$142.00	\$56,800.00
#68	5.21.A Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Less Than 6-ft Above Floor	210	SF	\$159.84	\$33,566.40	\$120.00	\$25,200.00	\$92.00	\$19,320.00	\$169.42	\$35,578.20	\$167.00	\$35,070.00
#69	5.21.B Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), 6-ft and Greater Above Floor	110	SF	\$183.32	\$20,165.20	\$131.00	\$14,410.00	\$98.00	\$10,780.00	\$194.31	\$21,374.10	\$181.00	\$19,910.00
#70	5.21.C Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Overhead	630	SF	\$202.25	\$127,417.50	\$153.00	\$96,390.00	\$110.00	\$69,300.00	\$216.53	\$136,413.90	\$188.00	\$118,440.00
#71	5.22.A Anti-corrosion Rebar Coating, Less Than 6-ft Above Floor	80	LF	\$8.59	\$687.20	\$16.00	\$1,280.00	\$52.00	\$4,160.00	\$9.10	\$728.00	\$18.00	\$1,440.00
#72	5.22.B Anti-corrosion Rebar Coating, 6-ft and	280	LF	\$10.61	\$2,970.80	\$16.00	\$4,480.00	\$54.00	\$15,120.00	\$11.24	\$3,147.20	\$23.00	\$6,440.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	Greater Above Floor												
#73	5.23.A Corner Spall Repair, Less Than 6-ft Above Floor	50	LF	\$254.78	\$12,739.00	\$82.00	\$4,100.00	\$97.00	\$4,850.00	\$270.06	\$13,503.00	\$167.00	\$8,350.00
#74	5.23.B Corner Spall Repair, 6-ft and Greater Above Floor	80	LF	\$209.07	\$16,725.60	\$82.00	\$6,560.00	\$99.00	\$7,920.00	\$221.61	\$17,728.80	\$178.00	\$14,240.00
#75	5.23.C Corner Spall Repair, Overhead	120	LF	\$227.51	\$27,301.20	\$82.00	\$9,840.00	\$112.00	\$13,440.00	\$241.15	\$28,938.00	\$208.00	\$24,960.00
#76	Lake Huron Water Treatment Plant Reservoir No. 3	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#77	6.14 Removal of settled material from reservoir interior	80	CY	\$80.00	\$6,400.00	\$120.00	\$9,600.00	\$80.00	\$6,400.00	\$96.35	\$7,708.00	\$88.00	\$7,040.00
#78	6.15 Supplemental Dewatering	30	DAY	\$1,886.40	\$56,592.00	\$3,474.00	\$104,220.00	\$1,300.00	\$39,000.00	\$1,191.65	\$35,749.50	\$1,104.00	\$33,120.00
#79	6.16.A Type I Crack Repair - Leaking Crack Repair, Less Than 6-ft Above Floor	530	LF	\$25.51	\$13,520.30	\$33.00	\$17,490.00	\$34.00	\$18,020.00	\$27.03	\$14,325.90	\$26.00	\$13,780.00
#80	6.16.B Type I Crack Repair - Leaking Crack Repair, 6-ft and Greater Above Floor	520	LF	\$29.04	\$15,100.80	\$41.00	\$21,320.00	\$37.00	\$19,240.00	\$30.78	\$16,005.60	\$27.00	\$14,040.00
#81	6.16.C Type I Crack Repair - Leaking Crack Repair, Overhead	5260	LF	\$29.55	\$155,433.00	\$56.00	\$294,560.00	\$38.00	\$199,880.00	\$31.32	\$164,743.20	\$29.00	\$152,540.00
#82	6.17.A Type II Crack Repair - Structural Crack Repair,	30	LF	\$59.34	\$1,780.20	\$76.00	\$2,280.00	\$42.00	\$1,260.00	\$62.90	\$1,887.00	\$29.00	\$870.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	Less Than 6-ft Above Floor												
#83	6.17.B Type II Crack Repair - Structural Crack Repair, 6-ft and Greater Above Floor	30	LF	\$61.87	\$1,856.10	\$76.00	\$2,280.00	\$44.00	\$1,320.00	\$65.57	\$1,967.10	\$30.00	\$900.00
#84	6.17.C Type II Crack Repair - Structural Crack Repair, Overhead	140	LF	\$36.11	\$5,055.40	\$76.00	\$10,640.00	\$46.00	\$6,440.00	\$38.27	\$5,357.80	\$34.00	\$4,760.00
#85	6.18.A RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#86	6.18.B RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#87	6.19.A Expansion Joint Repair - Type I	525	LF	\$12.12	\$6,363.00	\$16.00	\$8,400.00	\$16.00	\$8,400.00	\$12.85	\$6,746.25	\$11.00	\$5,775.00
#88	6.19.B RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#89	6.19.C Expansion Joint Repair - Type III	525	LF	\$40.91	\$21,477.75	\$131.00	\$68,775.00	\$68.00	\$35,700.00	\$43.36	\$22,764.00	\$323.00	\$169,575.00
#90	6.20.A Concrete Surface Spall Repair (Less than 2" in depth), Less Than 6-ft Above Floor	150	SF	\$62.37	\$9,355.50	\$82.00	\$12,300.00	\$42.00	\$6,300.00	\$66.11	\$9,916.50	\$93.00	\$13,950.00
#91	6.20.B Concrete Surface Spall Repair (Less than 2" in depth), 6-ft and Greater Above Floor	150	SF	\$87.37	\$13,105.50	\$98.00	\$14,700.00	\$45.00	\$6,750.00	\$92.61	\$13,891.50	\$102.00	\$15,300.00
#92	6.20.C Concrete Surface Spall Repair (Less	480	SF	\$127.77	\$61,329.60	\$131.00	\$62,880.00	\$52.00	\$24,960.00	\$135.43	\$65,006.40	\$136.00	\$65,280.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	than 2" in depth), Overhead												
#93	6.21.A Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Less Than 6-ft Above Floor	230	SF	\$142.16	\$32,696.80	\$120.00	\$27,600.00	\$87.00	\$20,010.00	\$150.69	\$34,658.70	\$161.00	\$37,030.00
#94	6.21.B Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), 6-ft and Greater Above Floor	230	SF	\$164.63	\$37,864.90	\$131.00	\$30,130.00	\$95.00	\$21,850.00	\$174.51	\$40,137.30	\$175.00	\$40,250.00
#95	6.21.C Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Overhead	750	SF	\$189.38	\$142,035.00	\$153.00	\$114,750.00	\$105.00	\$78,750.00	\$200.74	\$150,555.00	\$181.00	\$135,750.00
#96	6.22.A Anti-corrosion Rebar Coating, Less Than 6-ft Above Floor	80	LF	\$7.58	\$606.40	\$16.00	\$1,280.00	\$48.00	\$3,840.00	\$8.03	\$642.40	\$18.00	\$1,440.00
#97	6.22.B Anti-corrosion Rebar Coating, 6-ft and Greater Above Floor	540	LF	\$10.10	\$5,454.00	\$16.00	\$8,640.00	\$52.00	\$28,080.00	\$10.71	\$5,783.40	\$22.00	\$11,880.00
#98	6.23.A Corner Spall Repair, Less Than 6-ft Above Floor	50	LF	\$241.14	\$12,057.00	\$93.00	\$4,650.00	\$90.00	\$4,500.00	\$255.61	\$12,780.50	\$161.00	\$8,050.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

#99	6.23.B Corner Spall Repair, 6-ft and Greater Above Floor	220	LF	\$189.63	\$41,718.60	\$104.00	\$22,880.00	\$95.00	\$20,900.00	\$201.01	\$44,222.20	\$172.00	\$37,840.00
#100	6.23.C Corner Spall Repair, Overhead	290	LF	\$209.58	\$60,778.20	\$87.00	\$25,230.00	\$110.00	\$31,900.00	\$222.15	\$64,423.50	\$201.00	\$58,290.00
#101	7.0 Springwells Water Treatment Reservoir No. 1	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#102	7.14 Removal of settled material from reservoir interior	10	CY	\$80.00	\$800.00	\$120.00	\$1,200.00	\$80.00	\$800.00	\$96.35	\$963.50	\$88.00	\$880.00
#103	7.15 Supplemental Dewatering	30	DAY	\$1,886.40	\$56,592.00	\$3,474.00	\$104,220.00	\$1,300.00	\$39,000.00	\$1,191.65	\$35,749.50	\$1,104.00	\$33,120.00
#104	7.16.A Type I Crack Repair - Leaking Crack Repair, Less Than 6-ft Above Floor	1320	LF	\$26.01	\$34,333.20	\$33.00	\$43,560.00	\$36.00	\$47,520.00	\$27.57	\$36,392.40	\$27.00	\$35,640.00
#105	7.16.B Type I Crack Repair - Leaking Crack Repair, 6-ft and Greater Above Floor	1030	LF	\$27.27	\$28,088.10	\$37.00	\$38,110.00	\$39.00	\$40,170.00	\$28.91	\$29,777.30	\$28.00	\$28,840.00
#106	7.16.C Type I Crack Repair - Leaking Crack Repair, Overhead	1970	LF	\$31.06	\$61,188.20	\$47.00	\$92,590.00	\$40.00	\$78,800.00	\$32.92	\$64,852.40	\$29.00	\$57,130.00
#107	7.17.A Type II Crack Repair - Structural Crack Repair, Less Than 6-ft Above Floor	70	LF	\$28.03	\$1,962.10	\$56.00	\$3,920.00	\$44.00	\$3,080.00	\$29.71	\$2,079.70	\$29.00	\$2,030.00
#108	7.17.B Type II Crack Repair - Structural Crack Repair, 6-ft and	60	LF	\$33.59	\$2,015.40	\$62.00	\$3,720.00	\$46.00	\$2,760.00	\$35.60	\$2,136.00	\$31.00	\$1,860.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	Greater Above Floor												
#109	7.17.C Type II Crack Repair - Structural Crack Repair, Overhead	160	LF	\$42.68	\$6,828.80	\$62.00	\$9,920.00	\$48.00	\$7,680.00	\$45.23	\$7,236.80	\$35.00	\$5,600.00
#110	7.18.A Type III Crack Repair - Control/Construction Joint Repair, Less Than 6-ft Above Floor	14978	LF	\$6.82	\$102,149.96	\$11.00	\$164,758.00	\$15.00	\$224,670.00	\$7.23	\$108,290.94	\$5.30	\$79,383.40
#111	7.18.B Type III Crack Repair - Control/Construction Joint Repair, 6-ft and Greater Above Floor	15618	LF	\$8.34	\$130,254.12	\$11.00	\$171,798.00	\$17.00	\$265,506.00	\$8.83	\$137,906.94	\$5.30	\$82,775.40
#112	7.19.A Expansion Joint Repair - Type I	660	LF	\$11.87	\$7,834.20	\$28.00	\$18,480.00	\$17.00	\$11,220.00	\$12.58	\$8,302.80	\$11.00	\$7,260.00
#113	7.19.B Expansion Joint Repair - Type II	200	LF	\$40.91	\$8,182.00	\$131.00	\$26,200.00	\$60.00	\$12,000.00	\$43.36	\$8,672.00	\$102.00	\$20,400.00
#114	7.19.C Expansion Joint Repair - Type III	200	LF	\$40.91	\$8,182.00	\$153.00	\$30,600.00	\$69.00	\$13,800.00	\$43.36	\$8,672.00	\$332.00	\$66,400.00
#115	7.20.A Concrete Surface Spall Repair (Less than 2" in depth), Less Than 6-ft Above Floor	160	SF	\$60.60	\$9,696.00	\$82.00	\$13,120.00	\$45.00	\$7,200.00	\$64.24	\$10,278.40	\$96.00	\$15,360.00
#116	7.20.B Concrete Surface Spall Repair (Less than 2" in depth), 6-ft	80	SF	\$91.66	\$7,332.80	\$87.00	\$6,960.00	\$47.00	\$3,760.00	\$97.16	\$7,772.80	\$104.00	\$8,320.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	and Greater Above Floor												
#117	7.20.C Concrete Surface Spall Repair (Less than 2" in depth), Overhead	510	SF	\$136.86	\$69,798.60	\$109.00	\$55,590.00	\$55.00	\$28,050.00	\$145.07	\$73,985.70	\$139.00	\$70,890.00
#118	7.21.A Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Less Than 6-ft Above Floor	250	SF	\$144.69	\$36,172.50	\$120.00	\$30,000.00	\$89.00	\$22,250.00	\$153.36	\$38,340.00	\$164.00	\$41,000.00
#119	7.21.B Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), 6-ft and Greater Above Floor	120	SF	\$171.20	\$20,544.00	\$131.00	\$15,720.00	\$96.00	\$11,520.00	\$181.47	\$21,776.40	\$178.00	\$21,360.00
#120	7.21.C Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Overhead	790	SF	\$200.99	\$158,782.10	\$153.00	\$120,870.00	\$108.00	\$85,320.00	\$213.05	\$168,309.50	\$184.00	\$145,360.00
#121	7.22.A Anti-corrosion Rebar Coating, Less Than 6-ft Above Floor	110	LF	\$8.08	\$888.80	\$22.00	\$2,420.00	\$50.00	\$5,500.00	\$8.56	\$941.60	\$18.00	\$1,980.00
#122	7.22.B Anti-corrosion Rebar Coating, 6-ft and	320	LF	\$10.61	\$3,395.20	\$27.00	\$8,640.00	\$54.00	\$17,280.00	\$11.24	\$3,596.80	\$22.00	\$7,040.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	Greater Above Floor												
#123	7.23.A Corner Spall Repair, Less Than 6-ft Above Floor	90	LF	\$225.23	\$20,270.70	\$71.00	\$6,390.00	\$94.00	\$8,460.00	\$238.74	\$21,486.60	\$164.00	\$14,760.00
#124	7.23.B Corner Spall Repair, 6-ft and Greater Above Floor	210	LF	\$203.52	\$42,739.20	\$82.00	\$17,220.00	\$98.00	\$20,580.00	\$215.73	\$45,303.30	\$175.00	\$36,750.00
#125	7.23.C RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#126	8.0 Springwells Water Treatment Plant - Reservoir No. 2	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#127	8.14 Removal of settled material from reservoir interior	10	CY	\$80.00	\$800.00	\$120.00	\$1,200.00	\$80.00	\$800.00	\$96.35	\$963.50	\$88.00	\$880.00
#128	8.15 Supplemental Dewatering	30	DAY	\$1,886.40	\$56,592.00	\$3,474.00	\$104,220.00	\$1,300.00	\$39,000.00	\$1,191.65	\$35,749.50	\$1,104.00	\$33,120.00
#129	8.16.A Type I Crack Repair - Leaking Crack Repair, Less Than 6-ft Above Floor	1320	LF	\$24.50	\$32,340.00	\$33.00	\$43,560.00	\$39.00	\$51,480.00	\$25.96	\$34,267.20	\$28.00	\$36,960.00
#130	8.16.B Type I Crack Repair - Leaking Crack Repair, 6-ft and Greater Above Floor	1030	LF	\$27.53	\$28,355.90	\$36.00	\$37,080.00	\$42.00	\$43,260.00	\$29.17	\$30,045.10	\$29.00	\$29,870.00
#131	8.16.C Type I Crack Repair - Leaking Crack Repair, Overhead	1970	LF	\$31.57	\$62,192.90	\$47.00	\$92,590.00	\$43.00	\$84,710.00	\$33.46	\$65,916.20	\$30.00	\$59,100.00
#132	8.17.A Type II Crack Repair - Structural Crack Repair, Less Than 6-ft Above Floor	70	LF	\$28.54	\$1,997.80	\$56.00	\$3,920.00	\$46.00	\$3,220.00	\$30.24	\$2,116.80	\$30.00	\$2,100.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

#133	8.17.B Type II Crack Repair - Structural Crack Repair, 6-ft and Greater Above Floor	60	LF	\$34.34	\$2,060.40	\$62.00	\$3,720.00	\$48.00	\$2,880.00	\$36.40	\$2,184.00	\$32.00	\$1,920.00
#134	8.17.C Type II Crack Repair - Structural Crack Repair, Overhead	160	LF	\$43.18	\$6,908.80	\$57.00	\$9,120.00	\$50.00	\$8,000.00	\$45.77	\$7,323.20	\$36.00	\$5,760.00
#135	8.18.A Type III Crack Repair - Structural Construction/Control Joint Repair, Less Than 6-ft Above Floor	14978	LF	\$6.82	\$102,149.96	\$11.00	\$164,758.00	\$16.00	\$239,648.00	\$7.23	\$108,290.94	\$5.50	\$82,379.00
#136	8.18.B Type III Crack Repair - Structural Crack Repair, 6-ft and Greater Above Floor	15618	LF	\$8.34	\$130,254.12	\$11.00	\$171,798.00	\$18.00	\$281,124.00	\$8.83	\$137,906.94	\$5.50	\$85,899.00
#137	8.19.A Expansion Joint Repair - Type I	660	LF	\$12.38	\$8,170.80	\$31.00	\$20,460.00	\$18.00	\$11,880.00	\$13.11	\$8,652.60	\$11.00	\$7,260.00
#138	8.19.B Expansion Joint Repair - Type II	200	LF	\$41.92	\$8,384.00	\$136.00	\$27,200.00	\$62.00	\$12,400.00	\$44.43	\$8,886.00	\$106.00	\$21,200.00
#139	8.19.C Expansion Joint Repair - Type III	200	LF	\$41.92	\$8,384.00	\$136.00	\$27,200.00	\$73.00	\$14,600.00	\$44.43	\$8,886.00	\$343.00	\$68,600.00
#140	8.20.A Concrete Surface Spall Repair (Less than 2" in depth), Less Than 6-ft Above Floor	160	SF	\$61.11	\$9,777.60	\$82.00	\$13,120.00	\$47.00	\$7,520.00	\$64.77	\$10,363.20	\$98.00	\$15,680.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

#141	8.20.B Concrete Surface Spall Repair (Less than 2" in depth), 6-ft and Greater Above Floor	80	SF	\$92.42	\$7,393.60	\$87.00	\$6,960.00	\$49.00	\$3,920.00	\$97.96	\$7,836.80	\$107.00	\$8,560.00
#142	8.20.C Concrete Surface Spall Repair (Less than 2" in depth), Overhead	510	SF	\$138.88	\$70,828.80	\$82.00	\$41,820.00	\$58.00	\$29,580.00	\$147.21	\$75,077.10	\$142.00	\$72,420.00
#143	8.21.A Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Less Than 6-ft Above Floor	250	SF	\$148.47	\$37,117.50	\$114.00	\$28,500.00	\$92.00	\$23,000.00	\$157.38	\$39,345.00	\$167.00	\$41,750.00
#144	8.21.B Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), 6-ft and Greater Above Floor	120	SF	\$174.73	\$20,967.60	\$131.00	\$15,720.00	\$98.00	\$11,760.00	\$185.21	\$22,225.20	\$181.00	\$21,720.00
#145	8.21.C Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Overhead	790	SF	\$205.79	\$162,574.10	\$153.00	\$120,870.00	\$110.00	\$86,900.00	\$218.13	\$172,322.70	\$188.00	\$148,520.00
#146	8.22.A Anti- corrosion Rebar Coating, Less Than 6-ft Above Floor	110	LF	\$8.59	\$944.90	\$27.00	\$2,970.00	\$52.00	\$5,720.00	\$9.10	\$1,001.00	\$18.00	\$1,980.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

#147	8.22.B Anti-corrosion Rebar Coating, 6-ft and Greater Above Floor	320	LF	\$11.11	\$3,555.20	\$27.00	\$8,640.00	\$54.00	\$17,280.00	\$11.78	\$3,769.60	\$23.00	\$7,360.00
#148	8.23.A Corner Spall Repair, Less Than 6-ft Above Floor	90	LF	\$229.78	\$20,680.20	\$82.00	\$7,380.00	\$97.00	\$8,730.00	\$243.56	\$21,920.40	\$167.00	\$15,030.00
#149	8.23.B Corner Spall Repair, 6-ft and Greater Above Floor	210	LF	\$208.06	\$43,692.60	\$82.00	\$17,220.00	\$99.00	\$20,790.00	\$220.54	\$46,313.40	\$178.00	\$37,380.00
#150	8.23.C RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#151	9.0 Springwells Water Treatment Plant - Reservoir No. 3	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#152	9.14 Removal of settled material from reservoir interior	10	CY	\$80.00	\$800.00	\$120.00	\$1,200.00	\$80.00	\$800.00	\$96.35	\$963.50	\$88.00	\$880.00
#153	9.15 Supplemental Dewatering	30	DAY	\$1,886.40	\$56,592.00	\$3,474.00	\$104,220.00	\$1,300.00	\$39,000.00	\$1,191.65	\$35,749.50	\$1,104.00	\$33,120.00
#154	9.16.A Type I Crack Repair - Leaking Crack Repair, Less Than 6-ft Above Floor	1580	LF	\$26.26	\$41,490.80	\$33.00	\$52,140.00	\$43.00	\$67,940.00	\$27.84	\$43,987.20	\$29.00	\$45,820.00
#155	9.16.B Type I Crack Repair - Leaking Crack Repair, 6-ft and Greater Above Floor	1140	LF	\$27.78	\$31,669.20	\$36.00	\$41,040.00	\$46.00	\$52,440.00	\$29.44	\$33,561.60	\$30.00	\$34,200.00
#156	9.16.C Type I Crack Repair - Leaking Crack Repair, Overhead	3630	LF	\$31.31	\$113,655.30	\$46.00	\$166,980.00	\$47.00	\$170,610.00	\$33.19	\$120,479.70	\$32.00	\$116,160.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

#157	9.17.A Type II Crack Repair - Structural Crack Repair, Less Than 6-ft Above Floor	90	LF	\$32.32	\$2,908.80	\$57.00	\$5,130.00	\$49.00	\$4,410.00	\$34.26	\$3,083.40	\$32.00	\$2,880.00
#158	9.17.B Type II Crack Repair - Structural Crack Repair, 6-ft and Greater Above Floor	60	LF	\$34.85	\$2,091.00	\$62.00	\$3,720.00	\$51.00	\$3,060.00	\$36.94	\$2,216.40	\$33.00	\$1,980.00
#159	9.17.C Type II Crack Repair - Structural Crack Repair, Overhead	200	LF	\$35.86	\$7,172.00	\$62.00	\$12,400.00	\$54.00	\$10,800.00	\$38.01	\$7,602.00	\$37.00	\$7,400.00
#160	9.18.A Type III Crack Repair - Structural Crack Repair, Less Than 6-ft Above Floor	18950	LF	\$6.57	\$124,501.50	\$11.00	\$208,450.00	\$18.00	\$341,100.00	\$6.96	\$131,892.00	\$5.70	\$108,015.00
#161	9.18.B Type III Crack Repair - Structural Crack Repair, 6-ft and Greater Above Floor	19660	LF	\$8.84	\$173,794.40	\$11.00	\$216,260.00	\$20.00	\$393,200.00	\$9.37	\$184,214.20	\$5.70	\$112,062.00
#162	9.19.A Expansion Joint Repair - Type I	660	LF	\$12.63	\$8,335.80	\$27.00	\$17,820.00	\$20.00	\$13,200.00	\$13.38	\$8,830.80	\$11.00	\$7,260.00
#163	9.19.B Expansion Joint Repair - Type II	200	LF	\$42.68	\$8,536.00	\$131.00	\$26,200.00	\$65.00	\$13,000.00	\$45.23	\$9,046.00	\$111.00	\$22,200.00
#164	9.19.C Expansion Joint Repair - Type III	200	LF	\$42.68	\$8,536.00	\$131.00	\$26,200.00	\$77.00	\$15,400.00	\$45.23	\$9,046.00	\$355.00	\$71,000.00
#165	9.20.A Concrete Surface Spall Repair (Less than 2" in	190	SF	\$73.99	\$14,058.10	\$78.00	\$14,820.00	\$50.00	\$9,500.00	\$78.42	\$14,899.80	\$101.00	\$19,190.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

	depth), Less Than 6-ft Above Floor												
#166	9.20.B Concrete Surface Spall Repair (Less than 2" in depth), 6-ft and Greater Above Floor	90	SF	\$84.34	\$7,590.60	\$82.00	\$7,380.00	\$54.00	\$4,860.00	\$89.40	\$8,046.00	\$110.00	\$9,900.00
#167	9.20.C Concrete Surface Spall Repair (Less than 2" in depth), Overhead	620	SF	\$141.15	\$87,513.00	\$82.00	\$50,840.00	\$62.00	\$38,440.00	\$149.62	\$92,764.40	\$146.00	\$90,520.00
#168	9.21.A Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Less Than 6-ft Above Floor	300	SF	\$154.79	\$46,437.00	\$120.00	\$36,000.00	\$96.00	\$28,800.00	\$164.07	\$49,221.00	\$172.00	\$51,600.00
#169	9.21.B Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), 6-ft and Greater Above Floor	140	SF	\$191.65	\$26,831.00	\$131.00	\$18,340.00	\$101.00	\$14,140.00	\$203.15	\$28,441.00	\$186.00	\$26,040.00
#170	9.21.C Concrete Formed Spall Repair (Greater than 2", but not exceeding 6" in depth), Overhead	970	SF	\$209.33	\$203,050.10	\$153.00	\$148,410.00	\$115.00	\$111,550.00	\$221.88	\$215,223.60	\$193.00	\$187,210.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

#171	9.22.A Anti-corrosion Rebar Coating, Less Than 6-ft Above Floor	140	LF	\$9.09	\$1,272.60	\$27.00	\$3,780.00	\$55.00	\$7,700.00	\$9.64	\$1,349.60	\$18.00	\$2,520.00
#172	9.22.B Anti-corrosion Rebar Coating, 6-ft and Greater Above Floor	390	LF	\$11.62	\$4,531.80	\$27.00	\$10,530.00	\$58.00	\$22,620.00	\$12.31	\$4,800.90	\$23.00	\$8,970.00
#173	9.23.A Corner Spall Repair, Less Than 6-ft Above Floor	120	LF	\$203.27	\$24,392.40	\$82.00	\$9,840.00	\$101.00	\$12,120.00	\$215.46	\$25,855.20	\$171.00	\$20,520.00
#174	9.23.B Corner Spall Repair, 6-ft and Greater Above Floor	270	LF	\$209.83	\$56,654.10	\$82.00	\$22,140.00	\$105.00	\$28,350.00	\$222.42	\$60,053.40	\$183.00	\$49,410.00
#175	9.23.C RESERVED	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#176	10.0 Southwest Water Treatment Plant-Reservoir No. 1	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#177	10.14 Removal of settled material from reservoir interior	80	CY	\$80.00	\$6,400.00	\$120.00	\$9,600.00	\$80.00	\$6,400.00	\$96.35	\$7,708.00	\$88.00	\$7,040.00
#178	10.15 Supplemental Dewatering	30	DAYS	\$1,886.40	\$56,592.00	\$3,474.00	\$104,220.00	\$1,300.00	\$39,000.00	\$1,191.65	\$35,749.50	\$1,104.00	\$33,120.00
#179	11.0 Southwest Water Treatment Plant - Reservoir No. 2	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#180	11.14 Removal of settled material from reservoir interior	80	CY	\$80.00	\$6,400.00	\$120.00	\$9,600.00	\$80.00	\$6,400.00	\$96.35	\$7,708.00	\$88.00	\$7,040.00
#181	11.15 Supplemental Dewatering	30	DAYS	\$1,886.40	\$56,592.00	\$3,474.00	\$104,220.00	\$1,300.00	\$39,000.00	\$1,191.65	\$35,749.50	\$1,104.00	\$33,120.00

RFB BID TAB EVALUATION

Owner: Great Lakes Water Authority (GLWA)

Contract No.: 1900744

Title: Reservoir Rehabilitation Project at Imlay, Lake Huron, Springwells and Southwest Water Treatment Facilities

#182	12.0 Southwest Water Treatment Plant - Reservoir No. 3	0	LF	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
#183	12.14 Removal of settled material from reservoir interior	80	CY	\$80.00	\$6,400.00	\$120.00	\$9,600.00	\$80.00	\$6,400.00	\$96.35	\$7,708.00	\$88.00	\$7,040.00
#184	12.15 Supplemental Dewatering	30	DAYS	\$1,886.40	\$56,592.00	\$3,474.00	\$104,220.00	\$1,300.00	\$39,000.00	\$1,191.65	\$35,749.50	\$1,104.00	\$33,120.00
#185	GRAND TOTAL (Sum of Items 1-184)	1	LS	\$6,632,631.63	\$6,632,631.63	\$7,372,869.00	\$7,372,869.00	\$7,011,654.00	\$7,011,654.00	\$6,794,934.51	\$6,794,934.51	\$6,361,208.00	\$6,361,208.00