



Procurement Form (FOR)

Effective Date:
5/1/2019

Document #:
FSA_PRO_FOR_0041

Revision Date:
N/A

Revision#:
0

Document Title:
Vendor Response Follow-up

Document Owner/Department:
Procurement Team

Contract No./Title: RFB 2002048 Phase II – 14 Mile Transmission Main Loop Project – Double Disc Gates
Date: 9/16/2020

Vendor	Contact Name	Email Address	Explanation of No Bid Submittal
Emerson Automation Solutions	Rafael Fernandez	RafaelFernandez@Emerson.com	Bid was not submitted due to no scope associated with the Ovation Control System. If Emerson related scope was identified, the firm would have bid as a subcontractor, most likely.
Weiss Construction	Joe Mulville	jmulville@weiss-construction.com	We are a contractor, not a material supplier.
OHM Advisors	Erin Valmont	erinvalmont@ohn-advisors.com	We download relevant RFPs for review. Sometimes we are looking for a partnership opportunity.... For this one, another firm had brought up partnering.
Watertap, Inc.	Linda Carpani	linda@watertap, inc.com	Review of the GLWA bid request: It doesn't appear there were any line stops, valve insertions or live taps on this project. That was the reason Wiretap, Inc. did not submit a bid.
Joe Felan	Joe Felan	jpf_0@yahoo.com	The company is a contractor that deals with installation, not the purchase of materials/valves.
Dave Brochue	Dave Brochue	dbrochue@3bassociates.com	Reviewed RFB for informational purposes.
Rangeline Pipeline Services	Scott Noonan	SNoonan@Rangeline.com	We would have to get information from the supplier (already bidding) that may result in competing with the existing supplier.



Procurement Form (FOR)

Effective Date:
5/1/2019

Document #:
FSA_PRO_FOR_0041

Revision Date:
N/A

Revision#:
0

Document Title:
Vendor Response Follow-up

Document Owner/Department:
Procurement Team

Contract No./Title: RFB 2002048 Phase II – 14 Mile Transmission Main Loop Project – Double Disc Gates
Date: 9/16/2020

Vendor	Contact Name	Email Address	Explanation of No Bid Submittal
Mokveld USA, Inc.	Jimmy Tsiantopoulos	Jimmy.tsiantopoulos@mokveld.com	Mokveld Valves did not respond to RFB 2002048 because we do not manufacture/supply gate valves.